### Energy performance certificate (EPC)

157 Church Energy Valid14 Road rating HOLYWOOD BT18 9BZ Certi**3537** Certi**3537** numtla22-5580-1554-1292


Property Detached bungalow type

Total 143 square metres floor area

#### Energy efficiency rating for this property

This property's current energy rating is E. It has the potential to be D.

See how to improve this property's energy performance.



The graph shows this

property's current and potential energy efficiency.

Properties are given a rating from A (most efficient) to G (least efficient).

Properties are also given a score. The higher the number the lower your fuel bills are likely to be.

For properties in Northern Ireland:

the average energy rating is D theenergyaveragescore is 60

#### Breakdown of property's energy performance

This section shows the energy performance for features of this property. The assessment does not consider the condition of a feature and how well it is working.

Each feature is assessed as one of the following:

- very good (most efficient)
- good
- average
- poor
- very poor (least efficient)

When the description says "assumed", it means that the feature could not be inspected and an assumption has been made based on the property's age and type.

Feature	Description	Rating
Wall	Cavity wall, filled cavity	Average
Roof	Pitched, 300 mm loft insulation	Very good
Roof	Pitched, insulated (assumed)	Average
Window	Fully double glazed	Average
Main heating	Boiler and radiators, oil	Average
Main heating control	Programmer, TRVs and bypass	Average
Hot water		

Feature	Description	Rating
	From main system, no cylinder thermostat	Very poor
Lighting	Low energy lighting in 47% of fixed outlets	Good
Floor	Solid, no insulation (assumed)	N/A
Secondary heating	Room heaters, smokeless fuel	N/A

#### Primary energy use

The primary energy use for this property per year is 252 kilowatt hours per square metre (kWh/m2).

Environmer impact of this property This property's current environmental	rated properties. An average to household produces This property tor produces
impact rating is F. It has the potential to be E.	This property's to potential production
Properties are rated in a scale from A to G based on how much carbon dioxide (CO2) they produce. Properties with an A rating produce less CO2 than G	By making the recommend changes, you could reduce this property's CO2 emissions by 1.7 tonnes per year. This will help to protect the environmen

Environmental impact ratings are based on assumptions about average occupancy and energy use. They may not reflect how energy is consumed by the people living at the property.

## Improve this property's energy performance

By following our step by step recommendations you could reduce this property's energy use and potentially save money.

Carrying out these changes in order will improve the property's energy rating and score from E (47) to D (57).

Step	Typical installation cost	Typical yearly saving
1. Increase hot water cylinder insulation	£15 - £30	£27
2. Low energy lighting	£40	£47
3. Condensing boiler	£2,200 - £3,000	£226
4. Floor insulation (solid floor)	£4,000 - £6,000	£138
5. Solar water heating	£4,000 - £6,000	£42

Step

Typical installation cost

Typical yearly saving

6. Solar photovoltaic panels

£3,500 - £5,500

£360

#### Paying for energy improvements

You might be able to get a grant from the Boiler Upgrade Scheme (https://www.gov.uk/applyboiler-upgrade-scheme). This will help you buy a more efficient, low carbon heating system for this property.

#### Estimated energy use and potential savings

Based on average energy costs when this EPC was created:

Estimated£1542 yearly energy cost for this property

Potential £301 saving if you complete every step in order

The estimated cost shows how much the average household would spend in this property for heating, lighting and hot water. It is not based on how energy is used by the people living at the property.

#### Heating use in this property

Heating a property usually makes up the majority of energy costs.

Potential energy savings by installing insulation

The assessor did not find any opportunitie to save energy by installing insulation in this property.

# Contacting the assessor and accreditation scheme

This EPC was created by a qualified energy assessor.

If you are unhappy about your property's energy assessment or certificate, you can complain to the assessor directly.

If you are still unhappy after contacting the assessor, you should contact the assessor's accreditation scheme.

Accreditation schemes are appointed by the government to ensure that assessors are qualified to carry out EPC assessments.

#### Assessor contact details

Assessor's	Patricia Best
name	
Telephone	07788108883
Email	patricia@bestpro

## Accreditation scheme contact details

Accreditation	Stroma
scheme	Certification Ltd
Assessor ID	STRO032003
Telephone	0330 124 9660
Email	certification@str

#### **Assessment details**

Assessor's	No related party
declaration	
Date of	14 February
assessment	2023
Date of	15 February
certificate	2023
Type of	RdSAP
assessment	